

No. of Feed pumps) Diameter of ditto 3 3/4" Stroke 9 1" Can one be overhauled while the other is at work

RAMS, "REGISTER, NEWCASTLE".

TELEPHONE N° CENTRAL 5190 (3 LINES)



Lloyd's Register of Shipping.

Collingwood Buildings, Newcastle-on-Tyne.

J.L. Thompson & Co's S.S. No. 543.
Armstrong Whitworth & Co's M.E. No. 27.

NWC. REPORT NO. 75361

Spare Gear - to be examined at Sunderland.

- ✓ Two top end bolts and nuts.
- ✓ Four bottom end bolts and nuts.
- ✓ Fore main bearing bolts and nuts.
- ✓ A set of coupling bolts.
- A set of feed and bilge pump valves.
- Assorted bolts - nuts and iron.
- ✓ A set of piston rings.
- ✓ Two pairs bottom end bushes.
- ✓ Two thrust block shoes.
- ✓ ~~Two~~ ^{one} eccentric sheaves.
- ✓ 2 ~~Two~~ eccentric straps.
- ✓ One air pump rod.
- ✓ One slide valve spindle.
- 4 propeller blades.
- ✓ ~~Two~~ ^{one} piston rods.
- ✓ One bilge pump ram.
- One set safety valve springs.



© 2021

Lloyd's Register
Foundation

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

510-808-010-0155