

010309-010316-0044 1/2

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stl S.M.V. KYBRA*

Rpt. *Stn*

No. *8559*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

*P. Long*

Transverse No. *2754*

Depth "d"

Framing: Table No. *✓*

Description *Bull angle frame as approved*

Longitudinal No. *9078*

Proportions Length =  
Depth =

Deck Sheerstrake *as approved*

*Revised Rules*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed **✠ 100 A. I. (Steel)** "with freeboard," as recommended. The Summer freeboard of *3ft 4in* from centre of disc to top of statutory deck line at *-* deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

*1 D<sup>k</sup> (Stb)*

*Cell D.B 146' 250t, M.T. 12' 115t, F.P.T. 58t, A.P.T. 25t.*

*F.K, 6 B.H, pt Cem, Wlgs do A = CP.*

*P. B 135' F 42'.*



© 2021 Lloyd's Register Foundation  
*P.T.O.*

Sunhyar should be requested to ~~state~~<sup>state</sup> whether the frames in the long  
sp are bracketed, <sup>to the upper 5K</sup> or scarphed. If the latter to state the length of  
scarph.

*J. H. [unclear]*

*[Signature]*  
16.4.26



© 2021

Lloyd's Register  
Foundation

0044 2/2