

1520

December 6, 1938.

S.S. "CHARLES R. HUNTLEY"

Freeboards same as provisionally assigned.

It is noted that the hatch beams have been reinforced to Rule standard.

Panel door (inner) to be replaced by steel doors at engine room entrance. ✓

Lifelines to be fitted. ✓

Closing arrangements for air pipes to be supplied where necessary. ✓

FURTHER ALTERATIONS IN GREEN 9/6/42

REPRODUCED
BOND
MADE IN GREAT BRITAIN



© 2021

Lloyd's Register
Foundation

010328-010337-0153