

LONDON

COPY

LOYD'S REGISTER OF SHIPPING

NEWCASTLE-ON-TYNE, No. 115444

Port NEWCASTLE UPON TYNE.

7th November 1958.

This is to Certify that I have surveyed the Machinery of the s.s. "ENDERBY" 9495 gross tons of ton whilst in Drydock and afloat at Messrs. Swan, Hunter & Thames Richardson Limited, Wallsend, and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also that I will Recommend that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book

B.S. 11.58

and that her Machinery Classification Record be continued in the Book.

Parts now examined:

(C.S. Items only)

Reduction gearing, steering, machinery, fire extinguishing arrangements, Port 35 K.W. Diesel Driven Generator, Starboard 55 K.W., Diesel Driven Generator, Inboard and Outboard 50 K.W. Turbo Driven Generators and electrical installation.

T.P. Gibbeson

Engineer Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

T.P. GIBBESON.

ABS Auxiliary Boiler Survey
CS Continuous Survey of Engines
DBS Donkey Boiler Survey
ES Engine Special Survey
MBS Main Boiler Survey
MES Modified Survey of Oil Engines
OF Fitted for oil fuel (date) FP above 150°F.

SGS Steam Generator Survey
SPS Steampipe Survey
TS Tailshaft Survey
TS(CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, fault or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."