

COPY FOR LONDON OFFICE.

Lloyd's Register of Shipping.



Port P A L E R M O

8th October, 1958.-

This is to Certify that I have

Donkey

part

Surveyed the Boiler^s and Machinery of the M/V "ESSO ITALIA",
12175 tons gross of Genoa, on the 8th September, 1958. and sub-
sequently, whilst the vessel was in dry dock and afloat at Palermo,
on account of annual docking, boilers and machinery survey,

and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all
recommendations made by me in connection therewith have
been carried out to my satisfaction, and that I have

Recommended that the record^s of Donkey Boiler Survey 9/58.
and Continuous Survey of Engine (with date),

be made in the Register Book in the case of this vessel when
the survey has been completed.

Parts now examined:—

The propeller, after end of stern bush, sea connections and underwater fastenings.

M.E. (port & star'd) all cyls., covers, pistons, rods, valves & gears;
N°5 star'd connecting rods, top ends & guides.

M.E. driven scavenge pumps. (port & star'd).—The aux' condenser. Main
Engine S.W., Aux' Feed & Bilge Pumps.— Aux' circ., standby L.O., Aux'
Feed, Lub.Oil, for X-hd bearings (for'd star'd), main feed, Boiler o.f.
pumps. Port & Star'd lub.oil coolers. The Feed heater. Main (port &
star'd) and auxiliary air receivers, and safety devices.

Port & Star'd steam driven generators.

(R.M. Nicholson)

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member of the Surveyors, or other Officers or Agents of the Society."