

COPY

Lloyd's Register of Shipping.



Port Kobe.

15th May 1940.

CONTINUATION OF KOBE DAMAGE REPORT DATED 12th July 1939.

"A" DAMAGE.

This is to Certify that

Y. Hamada,

the undersigned Surveyor to this Society did at the request of Messrs. Hiroumi Syozi Kabusiki Kaisya, survey, without prejudice,

M.S. "KORYU MARU", 6680 tons gross, of Kobe, on the 17th April 1940 and subsequently, whilst the vessel lay afloat at Tama, for the purpose of ascertaining further the nature and extent of damage stated to have been caused by colliding with the M.S. "RYOYO MARU", of Yokohama, on the 20th June 1939 at Tomogashima Guide.

For further particulars see Log Books and Kobe Damage Report dated 12th July 1939.

The following permanent repairs, as previously recommended, have now been completed to my satisfaction.

Starboard side Shell Plating in way of No.1 Hold:-

No.3 plate in the strake 1st below upper deck sheer strake - renewed.

No.4 plate in the strake 2nd below upper deck sheer strake - renewed.

All removals replaced in good order.

Repairs hose tested on completion.

New and disturbed parts recoated where necessary.

(continued).

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Lloyd's Register
Foundation

010369 - 010377 - 0190½

COPY

(2)

Continuation of Damage "A" Report on the M.S. "KORYU MARU",
Kobe, 15th May 1940.

NOTE:- These two plates have each been renewed in two
lengths with a suitable shift of butts.

J. Hamada
Surveyor to Lloyd's Register.

Fee & Expenses as per account.



© 2021

Lloyd's Register
Foundation

010369-010377-0190½

This
"W"
berly
amsta
veyo
ligene

00 C.