

"Koyo Maru."

Yka. Apt 2499.

It is submitted the Yokohama Surveyors be informed it is concluded that a spare set of feed & bridge pump valves has been placed on board but as no mention of this is made in their report they should state whether this is so.

They should also be informed that the N.H.P. with forced draft is 513. & not 442 as reported. The fees should be amended accordingly.

W.D.

27/8/19

010369 - 010377 - 0290

Cargo light cables carrying / Amperes, comprised of / wires, each / S.W.G. diameter, /