

COPY

LLOYD'S REGISTER OF SHIPPING

MEIKAI BUILDING

No. 32, AKASHI MACHI,

TELEGRAMS: "REGISTER" KOBE

TELEPHONE: 2530 SANNOMIYA

KOBE, 17th December, 1925.

Messrs. Ishihara Koichiro,

K O B E

Dear Sirs,

S/S "MALAY MARU"

In order to complete the second Special Survey No.2 on the above vessel, the following remains to be done, and repairs carried out if found necessary:

- (1) Wood lining in bridge space accomodation spaces, Port & Starbd., to be removed for examination of plating and painting.
- (2) Bridge space to be scaled, examined and painted.
- (3) Tween deck bunkers (side and cross) to be scaled, examined and painted.
- (4) Margin Brackets and gusset plates in Nos.1, 2 and 3 holds to be again examined.
- (5) Weather decks (in fore and aft wells) to be further examined.
- (6) 2 centre grder plates in Fore Peak to be renewed.

I am, dear Sirs,

Yours faithfully,

A.D. Buchanan

SURVEYOR TO LLOYD'S REGISTER.

© 2020
Lloyd's Register
Foundation

610391-010404-0051