

New  
**SUNVALLEY**

Copy of supplement to Vancouver letter of  
11th January, 1944, with First Entry Report on "FORT YUKON".

The following First Entry Reports from Vancouver, B.C., should be modified so that under shell plating aft, on page 2, the bottom plating (four strakes) and bilge plating (one strake) read, in each case, .50" instead of .44".

<u>Shipbuilders</u>	<u>Hull No.</u>	<u>Ship's Name</u>	<u>Rpt. No.</u>
Burrard Dry Dock Co. Ltd. North Vancouver, B.C.	180	"Fort Columbia"	5942
	182	"Fort Bellingham"	5954
	184	"Strathcona Park"	5966
	186	"Fort St. Nicolas"	5990
	188	"For Sakisdac"	6006
	190	"Fort Machault"	6023
	192	"Beaton Park"	6046
Burrard (Vancouver) Dry Dock Co. Ltd. Vancouver, B.C.	181	"Fort Yukon"	5950
	183	"Wascana Park"	5956
	185	"Fort Massac"	5969
	187	"Fort Prudhomme"	6002
	189	"Fort Venango"	6018
	191	"Fort Orleans"	6035
	193	"Fort St. Croix"	6062
North Van Ship Repairs Ltd. North Vancouver, B.C.	127	"Fort Hall"	5952
	128	"Fort Clatsop"	5955
	129	"Fort Colville"	5970
	130	"Fort Panmure"	6001
	131	"Fort Marin"	6015
	132	"Fort Saleesh"	6025
	133	"Dundurn Park"	6045



© 2021

Lloyd's Register  
Foundation

010405-010415-0098



1.c.8

Printed by Dr  
S. J. J. J.

Print No.

Print's Name

Print No.

The following plates were taken from the original plates of the "100" series, in each case, the bottom plate (long series) and the plate bearing (one series) the letters "100". The plates were taken from the original plates of the "100" series, in each case, the bottom plate (long series) and the plate bearing (one series) the letters "100".



Lloyd's Register  
Foundation