

See also Endorsement dated 6.4.60.
Received from Chief Ship Surveyor

26 APR 1960

NAME "CAILLY" REPORT L.A. No. 8830

B

inding Conditions of Class: SUBJECT to shell plate No.1
2nd below sheer (s.s.f) and adjacent shell plate No.2 being
pecially examined and dealt with as necessary, also to extensive scaling
ing carried out to shell plating, deck plating and hatch coamings,
the Special Survey.

Appendix. (As before ~~or None~~)

of Present Survey: (Afloat and in dry dock)

ermanent repairs to leaky rivets etc.

endation:

SUBMITTED record of 'DS 3,60' be assigned
as recommended, subject as above, to indented shell
plates A.2 & B.1 (p.s.f) and to shell plating in
way of O.F.tanks (p & s) being specially examined
by the S.S.


S 3,60 Subject

N S.R.L. APPENDIX.

ndented plating (p & s).
ulwark plating slightly indented.

IT IS FURTHER SUBMITTED the Lloyd's Agents Surveyor
e advised it is concluded suitable repairs were effected to the hole in the
eel plating.

(new)



Lloyd's Register
Foundation
010405-010415-0127