

Lloyd's Register of Shipping.

(Report on Vessel No. 57275

Port

Glasgow

No.

SHIP FORGINGS OR CASTINGS.

I have to report that the undermentioned Iron or ~~Steel~~ Forgings or Castings, manufactured by Mrn T. S. Foster & son Ltd of Sunderland for the Vessel No. 338, being built by Mrn Scott & son Ltd of Bowling have been inspected by me as set forth below and found to be, so far as can be seen, Sound.

Mark on Forgings or Castings.

Lloyd's

No. 8671


JD 7.5.36

Tiller

J Dale
Sunderland
8.5.36

| | STERN FRAME. | RUDDER FRAME. | STEM. |
|---|--------------|---------------------|-------|
| Material* | | Scrap iron | |
| How made | | Forged & built | |
| If annealed | | | |
| Dimensions | | as per plan | |
| Progress on Inspection | | Forging & Machining | |
| Date when Inspected | | 7.5.36 | |
| CASTINGS. | | | |
| Tests on Standard Test Pieces. | | | |
| Tensile Test— | | | |
| Tons per square inch | | | |
| Extension per cent. ... | | | |
| Cold Bending Test— | | | |
| Angle before fracture | | | |
| Drop Test— | | | |
| Height from ground ... | | | |
| Hammering Test— | | | |
| If made according to Rules (and found satisfactory ...) | | | |

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Fee (if any chargeable) £ Manitiles 9/6

To be paid at

* If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

Scott & Sons.

N^o 338.

Ruader & Liller
Report.



© 2021

Lloyd's Register
Foundation