

ived by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SEL'S NAME

"JOSE DIAS"

Rpt. Lon.

No. 114036

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey COMPLETION OF SPECIAL SURVEY OF ENGINES-AND-BOILERS FOR S.S. No.

This Survey, ~~due~~ ^{now} partly held 9.45, & completely held now
~~completed~~, and the following repairs carried out (due to wear & tear):-

New superheaters fitted to both boilers. Steam pipes to
 to superheaters examined and tested. HP cylinder rebored and piston
 renewed. A new LP crosshead fitted.

It is submitted the vessel is eligible to remain as classed, with
 notation of BS 5.46 (185 lbs.) as recommended.