

**COPY**

# Lloyd's Register of Shipping,

71, Fenchurch Street, F.C.3.

9th November, 1946.

Dear Sir,

In confirmation of the verbal arrangements made with Engineer Captain Williams regarding the spare screwshafts for the five Admiralty Rescue Tugs of the "Bustler Class" which hold classification with this Society, I have to say that it is considered the two screwshafts now in Admiralty store should be placed on board the tugs based on Halifax, N.S. and Singapore, and that three additional spare shafts should be manufactured and kept in store in a United Kingdom dockyard for allocation to tugs sent to foreign bases.

A copy of this letter is being sent to C.C.R.T., Farnham House, and to the Society's Surveyors at Glasgow, Halifax and Singapore.

Yours faithfully,

Clerk to the  
Classification Committee.

The Director of Dockyards,  
Admiralty,  
Whitehall,  
LONDON, S.W.1.



© 2021

Lloyd's Register  
Foundation

010466-010477-203