

Report to Chief Surveyors.....

Received from Chief Surveyors.....

25 JUN 1945

VESSEL'S NAME "MEDIATOR"

REPORT

Gls.

No. 69666

For the CHIEF SHIP SURVEYOR ~~and~~ CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."— (Extract from Sub-Committee's Report, 24/5/42.)

Nature of Survey DOCKING

~~When done~~

NOTED
22.6.45



The Surveyors should be requested to state if they are in order in reporting only two ~~anchors~~ anchors on board and if so to furnish their recommendations accordingly. *This vessel was originally supplied with three bow anchors.*



© 2021

Lloyd's Register
Foundation

See correspondence re-hawse pipes.

010466-010977-0227