

Rpt. 8

## REPORT OF SHIP SURVEYS AND REPAIRS

Received London  
8 JUL 1963Ship's Name ~~NEW~~ MS "ALBACARA"

Gross tons 8247

Is there a rpt. 9? No

Port BUENOS AIRES Rpt. No. 35268

No. of visits One First date and Last date 27-6-63

Interim Cert. issued &amp; copy herewith? Yes Damage rpt. issued &amp; copy herewith? - Last rpt. (H.Q. only)

Date of completing rpt. 1-7-63

Surveyed at, if different from Port above Campana

Surveyed afloat and/or in D.D. Afloat

Last date of examination in D.D. -

Has a Load Line Survey been held? No

Freeboard Marks verified -

State which additional Rpt. 8 is attached: (C) (PS) (D) (R) (R)

Survey fees	Damage fee	Expenses
Part General Examination	-	\$ 600.00
\$ 15,000.00		

S.A. fee -

I have surveyed the above ship in accordance with the Rules for Completion of General Examination for postponement of Special Survey (C) due 1,63 .-

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

Note:- A considerable amount of wastage was observed in cargo tanks No.4 port and centre and No.5 port, centre and starboard. All the tanks having been satisfactorily cleaned for examination. (Please see Buenos Aires Report No.34973). It is considered however that the structure in way of the tanks examined will remain efficient during the period of postponement desired.

I recommend that this ship remain as classed with/without fresh record of dry docking Subject to any outstanding Conditions of Class being dealt with as previously recommended.-

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

J.H.C. Robertson

Surveyor to Lloyd's Register of Shipping

Date of Committee MONDAY 26 AUG 1963

Minute

Deferred for SS  
Subject  
(Postponement of SS  
until 1.64 approved)

D10484-010494-0085 1/2

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

Lloyd's Register  
Foundation

D



## Rpt. 8 (P.S.) TANKER

Ship's Name ~~XX~~ MS "ALBACARA"General Examination  
for postponement of Special  
S.S. ( ) Due Survey

Port BUENOS AIRES Rpt. No. 35268

Examined & condition		Examined & condition	
In dry dock from	-	* Hatchways	Good
" " " to	-	* Ventilators	Good
Shell plating	-	* Air & sounding pipes	Good
Sternframe	-	Doublers under sounding pipes	Good
Rudder	-	Steering arrangements (main)	-
Was rudder lifted?	-	" " (aux)	-
Plating, etc. in way of shell openings	-	Windlass	-
Side scuttles & deadlights	-	Masts & rigging	-
Overbd. scuppers & discharges	-	Hand pumps & suction	-
Hold	-	W.T. doors	-
F.P. spaces	Good	Bulwarks, freeing ports, etc.	-
Chain locker	-	Summer freeboard as verified	-
A.P. spaces	Good	<u>EQUIPMENT:</u>	
Engine space	Good	Equipment letter	
Boiler space	Good	Anchors: No. on board	
Under E. & B.	-	Cables {	State if ranged
Coal bunker	-		Length on board
Tunnel & well	-		Mean dias. range from to
Cement, asphalt, etc., on btm. shell	-		Rule length Dia.
Weather decks	-	Mooring ropes	
* Casings	-	Other items:	
* Deckhouses	-		
* Superstructures	-		
* Skylights	-		
* Companionways	-		

EXAMINED & CONDITION		TANKS	TESTED & CONDITION	
PORT	STARBOARD		PORT	STARBOARD
	Good	F.P. Tank		
	Good	A.P. Tank		
	-	Deep Tank No. 1		
	-	" " No. 2		

For other tanks see overleaf

\* These items to include their closing appliances

Where a part Special Survey and, say, dry docking Survey are held at the same time, the items for SS should be marked "For SS".

J. H. C. Robertson

Surveyor to Lloyd's Register of Shipping

Foundation



