

Surveyors.....

Received from Chief Surveyors.....

IE "APURE"

REPORT Jck. No. 2150

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

Docking: Equipment.

~~SKIPPED~~

NOTED.

Subject to 30 fathoms of chain cable (p.s.)

renewed at the earliest opportunity.

The Surveyors should be requested to state why they recommend 30 fathoms of chain cable to be renewed, as it would appear from the report the whole of the chain cable on board this ship is worn to renewal diameter, i.e. 1.23/32".

4/7/7.



© 2021

Lloyd's Register  
Foundation

010484-010494-0407