

Docking. Cracked screwshafts renewed,
together with M.E. cylinder liners -
A new aux eng driving a cargo pump fitted
alterations effected to cargo pumping engine.

It is submitted that this
vessel is eligible for THE
RECORD. S(N) 10.57

68.1. 2.4
14. 12. 57



© 2021

Lloyd's Register
Foundation