

23 OCT 1952

SHIP'S NAME 'MONTE SOLLUBE'

REPORT Bbo. No. 11252

Outstanding Conditions of Class:

Subject to holes in deck plating in way of Engineers' accommodation being permanently closed at the earliest opportunity.

ACTION is DEFERRED for examination in dry dock after grounding.

Endorsement of Class (B) (As before ~~or None~~)

Surveys due: A SPECIAL SURVEY (C) became due 3,51.

Nature of Present Survey: (~~Afloat and in dry dock~~)

Docking.
Damage - various causes.
Special Survey (C).
O.F. conversion.

Special Features:

Is Interim Certificate in order (Yes-~~No-None~~)

Items Outstanding: (If any for S.S. or A.S.)

S.S. to be completed by:

Recommendation: SUBMITTED record of docking 8,52 and Notation of 'ss.Bbo.8,52' be assigned as recommended, subject to E.W. repairs 8,52 to bottom of sternframe forward of aperture being specially examined at the next drydocking, but without other condition.

8,52 Bbo.) Subject
ss. Bbo. 8,52) Without.

DELETE FROM R.B.

"u"

2"

Coll BH to Sh dk, 5BH to U dk.

Cell DB 351' 1272t.

INSERT IN R.B.

"Fitted for oil fuel 8,52 F.P. above 150°F"

"z"

Coll BH to Sh dk, 6BH to U.dk.

Cell DB 351' pt W.B. 815t & pt O.F.

DTa O.F.



© 2020

Lloyd's Register
Foundation

P.T.O.

'MONTE SOLLUBE'

DELETE FROM S.R.L.

Drydocking (grounding).

ENDORSEMENT OF CLASS (B) (AMENDED).

Beams, etc. in bunker (p.s.) buckled (fire dam.)

W. O. T.

14. 10. 52



© 2020

Lloyd's Register
Foundation