

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

15th November 1963

C
RNC

Dear Sirs,

Steamer "ANGELIKI"

The Committee have today had before them the case of the above-named ship together with the Owners' letter of the 2nd forwarded with your memorandum of the 8th instant.

The position is that this vessel at present appears in the Register Book with a notation of "Repairs required - class suspended 7.63" and it is noted from the Owners' letter that the ship is now classed with the American Bureau.

As you know, when a ship is severely damaged and repairs are not carried out under the inspection of the Society's Surveyors it is the Committee's practice to assign a notation of "Class withdrawn - reported defects". It is concluded, however, that as the vessel is now classed with the American Bureau the necessary repairs have already received attention. If the Committee were assured on that point, in all probability they would assign a more neutral notation; so it will be very helpful if you are able to state from your local knowledge whether all repairs required by the American Bureau have been completed and the survey for classification with that Society carried out.

Yours faithfully,

Clerk to the
Classification Committee.

The Surveyors,
PIREAEUS.



Lloyd's Register
Foundation

010509 - 010518 - 0009

▲FRIDAY 29 NOV 1963

Defer again

Rmt.

At Eschrich Street, London, E.C.3

At Eschrich Street, London, E.C.3

LLOYD'S REGISTER OF SHILLING

COBY



© 2021

Lloyd's Register
Foundation