

27th June, 1961.

HAMBURG

10346, 501, 522, 576 - As recommended.

RMC 10568, 578 - As recommended.

10591 "MODAL" - As recommended, except that it is considered that the propeller should be backed off for further examination of the forward end of the screwshaft keyway by the end of May, 1962. The record of Screwshaft Examined 5.61 is being withheld meantime. You should, therefore, issue an amended Interim Certificate and forward a copy to this Office.



© 2021

Lloyd's Register
Foundation

010519-010525-0072