

Received from Chief Ship Surveyor.....

SHIP'S NAME "M O D A L" REPORT s (a) Osl. No. 9279
(b) Ham. No. 10591

Outstanding Conditions of Class:

NONE.

S.R.L. Appendix. (As before on ~~none~~)

Nature of Present Survey: (Afloat and in dry dock)

- (a) Examination afloat with a view to ship being towed to Lübeck.
- (b) Docking: Change of ownership:
Examination on account of damage - cause not stated.

Recommendation:

SUBMITTED record of 'DS 5,61' be assigned as recommended, subject to indented shell plate E.10 (p.s.) being examined and dealt with as necessary by the Special Survey.

DS 5,61 Subject

IN S.R.L. APPENDIX.

Some side shell plates (p & s) indented.
(Bottom plating to be kept under observation externally and internally at each drydocking). Last examined 11,59.

OFFICE NOTE

Docking brackets fitted - Nwc. 10,53.

Deck reinforced - Bal. 7,54.

Bottom reinforced - Nwc. 3,56.

Blk (new)



© 2021

Lloyd's Register
Foundation

010519-010525-0075