

LLOYD'S REGISTER OF SHIPPING



Port HAMBURG

26th May, 1961

This is to Certify that I have

Surveyed the Machinery of the T.S. "MODAL", 10720 tons gross of Oslo, whilst she lay in drydock and afloat at Lübeck on the 24th May, 1961 and subsequently for screwshaft survey,

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also that I will Recommend that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book

TSCL 5.61

and that her Machinery Classification Record be continued in the Book, subject to upper nest of air preheater tubes in stbd. boiler being renewed and boiler not being used in the meantime as previously recommended.

Parts now examined:

(C.S. Items only)

Vessel in drydock, propeller, stern bush, screwshaft, cocks, valves and outside fastenings of sea connections. WD 2.8 mm.

W.O. Dahlmann

(W.O. Dahlmann)

Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

