

to Chief Surveyors.....

Received from Chief Surveyors.....

SEL'S NAME ZEITOUN Ex (MOBILE BAY)

REPORT N. Yk.

No. 4958

21 OCT 1947

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

of Survey Docking, General Examination. When due.....

Repairs are required to shell plating etc.  
(S.S.) in way of No. 5. using tank and the equipment  
requires to be brought up to Rule requirements at  
first opportunity.

Insert in R. B.

100A1 "Carrying petroleum in bulk"  
(Classification contemplated)

8.47 N.Yk.

"Examined 8.47"



ADM.

© 2021 20-10447

BAM



Lloyd's Register  
Foundation

010519-010525-0131