

Ship Surveyor

Received from Chief Ship Surveyor

NAME "ITALY MARU" Rpt. Kob No. 11554

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

The 2nd Special Survey No. 2 has been partly held.

The year of grace expired 12.39, and a proposal to complete the Special Survey in 7.40 was agreed to.

Permanent repairs are required to some deck plates in lower tween deck bunker and after peak tank top plates which were found thin.

A bower anchor and a length of chain cable on board require to be tested.

Collision damage to No. 1 plate in 5th strake below sheer (p.s.a.), found slightly indented, requires to be dealt with at the Owners' convenience.

The KOBE Surveyors now report the vessel placed in dry dock and collision damage repairs, as above, effected.

The 2nd Special Survey No. 2 has now been completed, permanent repairs effected to deck and after peak tank top plates, as above, and additional wear and tear repairs effected by the renewal of 2 shell plates, repairs to four tank top plates, some 'tween deck frames, and minor repairs effected.

The Surveyors now forward particulars of the bower anchor and chain cable, as above, tested by the Japanese Classification Society. The Owners state that they are unable to obtain Lloyd's tested equipment and request that this equipment be accepted in this instance.

It is submitted the Owners' request be conceded.

It is further submitted the vessel is worthy to remain as classed with record of survey 7.40 and notation of 2nd S.S. No. 2-39 as recommended.

100A1
Awning dk with freeboard
7.40 Kob
S.S. Kob No. 2-39.

Delete from S.R.L

was
4.9.40
010526-010536-0006



© 2020

Lloyd's Register
foundation