

COPY

LLOYD'S REGISTER OF SHIPPING

Palermo Rpt.
No. 964



Port PALERMO

19th June 1963.

This is to Certify that I have surveyed part of the machinery of the S/S "MOBIL FLAME" 17598 Gross tons, of Panama, for Completion of Machinery Survey, Boiler and Docking Surveys,

and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned E.S. 5/62 as previously recommended, and MBS. 6/63 now, subject to any outstanding conditions of class being dealt with, as previously recommended.

Parts now examined:—

For Docking Surveys:— Propeller, after end of stern bush, underwater fastenings, sea connections.

For Main Boiler Surveys:— Port & Starboard Boilers in their entirety.

For Completion of E.S.:— Main L.P. Turbine.
Port & Starboard forced draught fans.
Inboard turbo generator auxiliary engine and gearing.

R. A. Lorraine
(R. A. Lorraine)

Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	MBS	Main Boiler Survey	TS	Tailshaft Survey
CSM	Continuous Survey of Machinery	OF	Fitted for oil fuel (date) FP above 150°F.	TS(CL)	Tailshaft Survey—Continuous Liner
DBS	Donkey Boiler Survey	SGS	Steam Generator Survey	TSN	Tailshaft renewed
ES	Engine Special Survey	SPS	Steampipe Survey	TS(OG)	Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."