

COPY

Ship's name "MOBIL FLAME"

Port RCT

No. 57176

Last survey date 15.11.63

Class is subject to NIL

Machinery Repairs.

Repairs effected to steam driven windlass on account of damage. Spare piston rod fitted and cylinder cover renewed with fabricated steel. Repairs also effected to starboard/draught fan electric motor armature.

IT IS SUBMITTED that this vessel is eligible to remain as classed.



© 2021

Lloyd's Register
Foundation