

Ship's name "MOBIL FLAME"

Port

ROT

9 - DEC 1963

No 57176

Class is subject to NIL

Last survey date 15.11.63

Machinery Repairs.

Repairs effected to steam driven windlass on account of damage. Spare piston rod fitted and cylinder cover renewed ~~with~~ <sup>renewed</sup> fabricated steel. Repairs also effected to starboard draught fan electric motor armature.

IT IS SUBMITTED that this vessel is eligible to remain as classed.



© 2021

Lloyd's Register  
Foundation

6.12.63