

Class is subject to

8 AUG 1962

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME.....

"SAIBURI"

REPORT.....

Bgk

3735

Bgk

No. 3733

Docking screwshaft examined and replaced by spare shaft due to worn liner.

CSM advanced.

Temporary repairs now effected to driving gear wheel with built in spring coupling for scavenge air blower.

Gear wheel ring was slightly damaged but teeth undamaged. The gear wheel to blower teeth were damaged, temporary repairs have now been effected and a complete unit has been ordered from makers and will be fitted at the earliest opportunity.

IT IS SUBMITTED that this vessel is eligible to remain as classed with fresh record of TSCL 5.62 now subject to the driving gear wheel unit of the scavenge air blower being renewed at the earliest opportunity.



© 2021

Lloyd's Register
Foundation

010537-010544-0174