

COPY.

LLOYD'S REGISTER OF SHIPPING



RPT. No. 31417.

Port BUENOS AIRES

Date 21st March, 1960.

This is to Certify *that I have*
Surveyed the T.E.Tanker "SAN JULIAN", 10448 tons gross of
Buenos Aires, on 1st December 1959 and subsequently whilst the
vessel lay afloat at this port, on account of damage stated due
to contact with S.S. "BARON BERWICK" on 26th November 1959,
whilst the "San Julian" lay alongside at New Port "E",
Buenos Aires.

and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report, stating that all repairs recommended by
me have been completed to my satisfaction, also that I will
Recommend *that she be* continued as now classed, without
fresh record of survey.

James S Cook

Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

J. S. Cook.


AS Annual Survey
 BiS Biennial Survey
 DS Docking Survey
 NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey
 SS(Dr) Hull Special Survey (Drilling)
 SS(M) Hull Special Survey (Modified)
 SS(P) Hull Special Survey (Progressive)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B)



010545-010553-0179