

30 JAN 1961

Received by Chief Ship Surveyor
GB

Received from Chief Ship Surveyor

SHIP'S NAME "A T L A S" REPORT Rot. No. 50663

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/62.)

This ship was built at Flushing in April 1960.

The ROTTERDAM Surveyors report (12,60), the ship placed in dry dock and on account of damage sustained by striking quay wall, repairs effected to locally indented shell plates in way of Nos. 2 & 4 holds.

It appears the ship has been laid up and has therefore been generally examined with a view to advancing the date from which the Special Surveys date, and found satisfactory.

IT IS SUBMITTED the ship is eligible to remain as classed, with record of 'DS 12,60' assigned as recommended.

DS 12,60.

INSERT IN R.B.
SS to date from 12,60.

IN S.R.L. APPENDIX.
(Main structure partly of P.403 Steel).

W.F.
24.1.61.



© 2021

Lloyd's Register
Foundation