

28 NOV 1960

SHIP'S NAME "SEIHO MARU" REPORT Kob. No. 8307

GB

standing Conditions of Class: SUBJECT to sternframe solepiece
(E.W. 1,60) being specially examined next drydocking.

R.L. Appendix. (As before ~~on None~~)

ture of Present Survey: (Afloat and in dry dock)

Docking: Minor wear and tear repairs:
Permanent/deferred damage repairs (contact):
Further E.W.repairs to sternframe.

commendation:

SUBMITTED record of 'DS 10,60' be assigned
subject to sternframe solepiece (E.W. 10,60 and
previously) being specially examined also to
indented shell plates H.9, J.9, L.9 & 10 and
M.9 & 10 (s.s.) in way No.7 wing cargo oil
tank being specially examined and dealt
with as necessary next drydocking.

DS 10,60 Subject
Amended.

IN S.R.L. APPENDIX.

No.5 D.B.tank top and lub.
oil drain tank top pitted.

OFFICE NOTE

Structural arrangements in order - 14.2.55.

Blk (new)

010580-010588-0139

