

"SHEAF MEAD"

It is submitted Messrs. W.A. Souter & Co.Ltd., be informed in reply to their letter of 23.7.48 that in addition to the items enumerated in this letter the following also require to be dealt with to complete the Special Survey:-

- Tween deck F.W. tank to be tested.
- * E.R. D.B. tank to be examined.
- Tunnel watertight door to be altered to comply with the Rules. *and A First Entry Report to be completed by the Society's Surveyors.*

They should also be informed that the date of Special Survey will be 6.47 as the principal part of the requirements was then complied with. If, however, an up to date notation is required, a General Examination of the parts already examined would require to be **made** to ascertain that no material deterioration has transpired.

* Engine Room Double bottom tank

For Mr. Pender
from Mr. Owen:

W.O.T.
26.7.48.

2021
Lloyd's Register
Foundation

Lloyd's Register
Foundation

Rec 27/7/48 010615-010623-0222