

DISCLOSED SECTION

(Received at London Office 559)

No. 117585 A

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When landed in at Local Office 19... Port of London

No. in Reg. Book 23464 Survey held at on the Wood, Iron or Steel SS. RICARDO R Date, First Survey Last Survey 19

Tonnage: GROSS 1542 UNDER DK 1424 NET 931 Built at Bilbao By whom Astilleros del Nervion When 1916 MONTH 9

Owners Hijos de Ramon A Ramos Soc. Owners' Address Anon. Managers Port belonging to Barcelona

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

Cell D Bor D Ba feet; uE & B feet; f feet; total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. BC Summary Port No 1976

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Failed or Repaired								
Failed or Repaired in place ...								


PRESENT CONDITION OF THE	
Decks	Bulkheads
Caulking of Decks	Ceiling
Coamings	Cement or Asphalt
Beams & Fastenings	Rudder
Outside Plating	Steering gear and its connections
" " In way of sidelights	Windlass
Frames	Have pumps been examined and found efficient?
Reverse Frames	Have Sluice Valves been examined and found efficient?
Longitudinals	Have Watertight Doors been examined and found efficient?
Transverses	Have Ventilators and their Coamings been examined and found efficient?
Floors	Air and Sounding Pipes
Keelsons	Doubling Plates under Sounding Pipes
Stringers	Engine Room Skylights
Inner Bottom Plating	Coal Bunkers, Openings, Covers, &c.
Have the Tanks been examined Internally?	Oil Bunkers
Have the Tanks been tested?	Scuppers
	Cargo Hatchways
	Hatches
	Planking
	Caulking
	Treenails
	Breasthooks & Stemson
	Transoms, Pointers & Crutches
	Timbers of Frame at openings
	" " at other places
	Stringers, Clamps & Shelves
	Salting
	State if examined.
	Copper, or Y.M. (State if on Felt.) When fitted, Month Year
	Boats
	Masts, Yards, &c.
	Condition, how ascertained (State if wedges removed.)
	Equipment letter
	Anchors. No. of
	Cables (State if now ranged)
	" length mean diam. (on board.)
	" Rule length size
	Chain Locker
	Hawsers & Warps
	Standing and Running Rigging
	Sails

General Observations, Opinion as to Class, Recommendation, &c. :— State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	10
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	10

Committee's Minute FRI. 31 MAR 1950 Character Assigned BS class withdrawn 3.50

116 MAR 1950



MADE AND PRINTED IN ENGLAND. (The Surveyors are requested not to write on or below the space for Committee's Minutes.)

Certificate required? If so, to be sent to

Surveyor to Lloyd's Register of Shipping. General Committee Thursday 13 April 1950

010624-010630-0037