

16 DEC 1936

Surveyors

NAME

Ricardo R.

Received from Chief Surveyors

Report

No.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case that the Classing Committee may have all the salient points presented in the endorsement." - (Extract from Sub-Committee's Report, 24/5/92.)

Donkey Boiler SURVEY PARTLY HELD.

11.31

When proposed to be completed

held, &c.

To complete the Survey of the Donkey Boiler for the record BS 9.35, the Safety valves require to be adjusted under steam.

The vessel is laid up

It is submitted that
this vessel is eligible for
THE RECORD.

BS 9.35 Subject to the Donkey Boiler safety valves being adjusted under steam

© 2021
Boyd's Register
Foundation

010624 - 010630 - 0054