

2m, 7, 16.

Received by Chief Ship Surveyor 11.10.16.

Received from Chief Ship Surveyor

VESSEL'S NAME S.S. "MIDELA NO. 2" Rpt. Bbo. No. 4829

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/12.)

Nature of Survey

It is submitted before this case receives consideration the Surveyors should be requested to state clearly whether the ceiling has been fitted in the hold as stated on the report, also whether a hand pump has been fitted in the fore peak and whether the stiffeners to the bulkheads on frames 44 and 65 are bulb angle as required.

They should also be informed that in future cases the plan should be amended to agree with the ship as built and with the 1st Entry report.

Ltr. Bbo. 11th

E. B. L.

11.10.16



© 2021

Lloyd's Register
Foundation

010624 - 010630 - 0072