

LONDON

COPY.

# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER



SS " ARION  
 MS  
 TO ACCOMPANY BUENOS AIRES REPORT N° 26414  
 Port BUENOS AIRES  
 DATED 5-Dec-55

5th. December, 1955.-

*This is to Certify that I have*

*Surveyed the steel screw steamer "ARIQN", 56.72 tons gross of  
 Panama, on the 14th. November 1955 and subsequently, on account  
 of vessel having had to anchor at Buoy 365, River Paraná, due  
 to stormy weather whilst on voyage Buenos Aires to Rosario on  
 the 10th. November, 1955,  
 and that I have transmitted to the Committee of Lloyd's  
 Register of Shipping, London, a Report, stating that all repairs  
 recommended by me have been completed to my satisfaction, and  
 that I have Recommended that she be continued as classed,  
 without fresh record of survey, subject to starboard anchor  
 chain cable being specially examined at next drydocking, also  
 to 15 fathoms of chain cable being supplied at earliest  
 opportunity also subject to all other conditions attached to the  
 vessel's class being dealt with as previously recommended,  
 being fit to carry dry and perishable cargoes.*

*J. White*  
Surveyor to Lloyd's Register.

FOR H. GITTINS (ACTING SURVEYOR)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof or the Surveyors, or other Officers or Agents of the Society."

(Cert. B)

© 2020

Lloyd's Register  
Foundation

010631-010639-0029