

Rpt. 8.

(Received at London Office 115 MAR 1955)

No. 25697.

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 14-3-1955. When handed in at Local Office 14-3-1955. Port of SWANSEA.

No. in Survey held at Swansea. Date, First Survey 28-1-55. Last Survey 1-3-1955.
Reg. Book (No. of Visits 2.)

56516 on the Wood, Iron or Steel SS "CLYNE CASTLE".

TONNAGE: Built at Selby. By whom Cochrane & Sons, Ltd. When 1929. YEAR. MONTH. 1.

GROSS 307 Owners Consolidated Fisheries, Ltd. Owners' Address (If not already recorded in Appendix to Register Book)

UNDER DK 267 Managers Sir John D. Marsden, Bt. Port belonging to Swansea.

NET 117

Surveyed Afloat or in Dry Dock? Dry Dock. Name of Dock Consolidated D.D. Destined Voyage -

Cell DBor DBa feet; uE&B feet; f feet

total capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Now. Last Report, No. 2553 Port SWS

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Survey should be summarized. Should the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs or alterations of Damage (the cause of which must be stated) should be separated from Repairs due to other causes and be included in the body of the report, should be summarized in the form shown below. Whenever the replacement of Machinery or other parts of the vessel, the particulars should be clearly stated in the space provided on the back of this form. State also the date and initials of the Surveyor in respect of this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE FOR DOCKING.

Vessel placed in dry dock. Bottom and rudder cleaned, examined, and coated.
Weather decks, hatches, ventilators, coamings, superstructure, windlass, steering gear examined and placed in order.

Vessel undocked 2-3-55.

Repairs.

Rudder lifted and Pintles rebushed. Wood streamlining at lower part renewed.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors.	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Replaced or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Decks	Good.	Good.	(State if on Felt.)
Caulking of Decks	Good.	Good.	When fitted, Month Year
Coamings	Good.	Good.	Boats
Beams & Fastenings	Good.	Good.	Masts, Yards, &c.
Outside Plating	Good.	Good.	Condition, how ascertained from deck.
" " in way of sidelights	Good.	Good.	(State if wedges removed.)
Frames	Good.	Good.	Equipment letter
Reverse Frames	Good.	Good.	Anchors, No. of
Longitudinals	Good.	Good.	Cables (State if now ranged) No.
Transverses	Good.	Good.	" length mean diamr.
Floors	Good.	Good.	(on board.)
Keelsons	Good.	Good.	" Rule length size
Stringers	Good.	Good.	Chain Locker
Inner Bottom Plating	Good.	Good.	Hawsers & Warps
Have the Tanks been examined internally?	Good.	Good.	Standing and Running Rigging
Have the Tanks been tested?	Good.	Good.	Sails

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether or not, in what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example, "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1-3-55," or "to remain as classed and to have record of survey, 1-3-55, and the notations of ss No. 1-38."

This vessel is in efficient condition and eligible in my opinion, to remain as classed with a fresh record of docking 3-55.

Survey Fee (per Section 23)	£	-	-	-	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 23)	£	-	-	-	Received by me,
Travelling Expenses (if chargeable)	£	-	-	-	19
Second Surveyor's Fee (if any)	£	-	-	-	19

Committee's Minute

Character Assigned

TUESDAY - 5 APR 1955

3.55 SWS.

S(N) 3.55

BS 3.55.

Surveyor to Lloyd's Register of Shipping.



© 2020

Lloyd's Register

010631-010639-0077

Is Certificate required? Yes to be sent to