

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE

010631-010639-0078

2 E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SHIP NAME "CLYNE CASTLE"

REPORT

Sws No. 25697

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/22.)

of Survey ~~COMPLETION OF~~ SPECIAL SURVEY OF ENGINES AND BOILERS

This Survey, due 9,54 ~~now~~ held, and screwshaft seen ~~not~~

~~completed~~, and the following repairs carried out (due to wear & tear):-

Screwshaft found wasted and cracked at top of cone and now renewed. Minor repairs effected to boiler.

It is submitted the vessel is eligible to remain as classed, with

notation of BS 3,55 S(N)CL 3,55

as recommended.



Lloyd's Register Foundation

1.4.55.