

5m.7.30.

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME _____

M. S. "PRAYDA"

Report _____

Levi

No. *98435*

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/23.)

Nature of Survey _____

Damage


When due _____

*Subject to indented side & bottom plating being repaired
in 3 months time.*

[Signature]

N.B.
23.3.31.

? *Repairs to be carried out
in Russia*



© 2020

Lloyd's Register
Foundation

010631-010639-0178