

Do. of Force
Do. of House
Do. of excess
Do. above C
Engine R

5.)

by Chief Ship Surveyor 29. 12. 05

Received from Chief Ship Surveyor

EL'S NAME *Ste. S. S. "Admiral"* Report *Brw.* No. *1231*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey *First entry*

It is submitted that before the case reaches the consideration of the Committee the Glasgow Surveyors should be informed that it has been arranged for the vessel to be supplied with a towline 75 fathoms ^{as required by Table 22} of 6 1/2" at their port, and they should be requested to see that this is done, and to report the fact in reporting upon the completion of the vessel to the Committee.

Ltr. to Glasgow 29/12/05

C. H. J.
29/12/05



© 2021

Lloyd's Register
Foundation

010687-010696-0299

PILLAI

"

"

WEBB