

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

FOUNDED 1780.


RE-CONSTITUTED 1834.

Certificate of Class

Twin Screw Steam Tug "SAMSON"
Official Number — Port of Registry —
Owners The Admiralty.
Builders, and where and when built Alexander Hall and Co., Ltd., Aberdeen, March, 1954.

REGISTERED PARTICULARS.

Length	167.10 feet	Tonnage, Gross	854.66
Breadth	35.20 feet	Ditto under Deck	659.51
Depth	16.45 feet	Ditto Net	184.18

This is to Certify that this Ship has been built under the Special Survey of the Surveyors to this Society, and was reported to be, on the 31st March, 1954 in a fit and efficient condition as is prescribed by the Society's Rules and has been CLASSED and entered in the REGISTER BOOK of this Society, with the Character  100A1

For Towing Services.


Fitted for oil fuel 3,54 flash point above 150°F.


subject to Periodical Surveys as required by the Rules.

The approved minimum freeboards from the deck line are as follows:—

Tropical	2 feet 7¼ inches (T).	Winter	} 3 feet 5 inches (WNA).
Summer	2 feet 11 inches (S).	North Atlantic	
Winter	3 feet 3 inches (W).	Allowance for fresh water for all freeboards	} 3½ inches

Witness my hand,


pro Secretary,


Chairman.

71, Fenchurch Street, London, E.C.3. 29th April, 1954.

N.B.—If the ship herein named proceed to sea with a less freeboard than that approved by the Committee, or if the freeboard marks be obliterated or placed higher than the correct position, the class will be liable to be forfeited.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

14.4



© 2021

Lloyd's Register
Foundation

010697-010704-0099