

BY AIRMAIL

11th December, 1956.

HONG KONG.

13292, 317, 24, 42 - As recommended.

RMC 13294, 344 - As recommended.

13279 and 13301 "LC 28" )  
13278 and 13300 "LC 25" )      The records of docking survey have  
in accordance with the usual practice in cases of ships laid up, the  
records of DBS 10,56 have also been assigned subject to the Boiler safety  
valves being adjusted under steam and the oil burning system examined  
under working conditions before the vessel is placed in commission.

Assignment of the Special Survey notations is, however, still  
in abeyance, as recommended by you, until the equipment has been placed  
in order.



Lloyd's Register  
Foundation

010705-010711-0016