

MEMORANDUM

31 OCT 1956
31 OCT 1956

COPY

LLOYD'S REGISTER OF SHIPPING, 71, FENCHURCH STREET,
LONDON, E.C.3.
UNITED WITH THE BRITISH CORPORATION REGISTER

(Ref. H.)

Surveyor(s) at HONG KONG

Date: 19th October, 1956.

Name: Lighters "L.C.25" & "L.C.28"

QUESTION

ANSWER

With reference to my letter the 28th March and yours of the 13th April, I shall be glad to learn how this case now stands.

The Owners' intention regarding the carrying out of the Donkey Boiler Surveys, due at the end of September and August respectively, and further examinations in drydock, will be appreciated.

Date:— 23rd October, 1956.

Both Lighters have been examined on drydock but the equipment has not yet been verified or tested. We understand that the anchors and cables will be tested in the near future.

Both Donkey Boilers on each Lighter have been examined internally but the safety valves will not be adjusted until early next year.

No Load Line survey has been carried out as the vessels are not in commission.

Certificates and reports on Docking and part Donkey Boiler Surveys have been or will be forwarded.

010705- 010711-0020

© 2021
Lloyd's Register
Foundation

