

12.20

40  
50  
40  
40  
87  
36  
38  
34  
48  
50  
48  
46  
42  
42  
40  
30  
32  
24  
K  
Deck is

to Chief Surveyors

Received from Chief Surveyors

SEL'S NAME *J. S. S. "Louchita"* Report *Gls.* No. *A 3751.*

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/02.)

of Survey *1<sup>st</sup> Entry.* When due

*+ 100 AI (Steel) with freeboard carrying petroleum in bulk.*

*1 Dk (Stl) Longitudinal framing ~~and~~ at bottom and <sup>at</sup> deck.*

*W.B. = F.P.T. 109T. A.P.T. 87T.*

*FK. 8 B.H. pt. cam. Lloyds A.T.C.P.*

*R.Q.D. 87' Trunk 176' F 42' Mch. aft.*

*[Signature]* *R.H.*  
*4.4.24*

*The Surveyor should be requested to forward the forging or casting reports.*

