

4E

30 APR 1957

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

ME

"ELA".

REPORT

Rot.

N 43184.

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

# REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH

Difficulties reported in the starboard main engine lub. oil pump and the steam driven auxiliary lub. oil pump. These pumps now renewed.

Some machinery parts examined.

IT IS SUBMITTED that this vessel is eligible to remain classed.

29.4.57.

© 2021

Lloyd's Register  
Foundation

010755-010765-0010