

Chief Surveyors 2.1.33.

Received from Chief Surveyors

4- JAN 1933

NAME *Sta. S. CIERTO*

Report

Cd

No. 1339.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)

2nd No. 1

SURVEY PARTLY HELD.

11.31

When proposed to be completed

f Survey held, &c.

The class of this trawler is subject to repairs being effected to chafed shell plating on port and starboard sides.

The 2nd S.S.No.1 has been partly held (for what remains to be done see Cadiz report No.1339 and Cadiz letter 28.10.32).

Some repairs are required.

Action has been deferred by the Committee from time to time and the Cadiz Surveyor now states that he is experiencing difficulty in obtaining definite information as to when the survey will be carried out. He has explained to the Owner that unless the vessel is submitted for survey at an early date he is afraid that the Committee will be obliged to take action regarding the class. He states that he will keep in touch with the Owner and report developments.

It is submitted for the consideration of the Committee as to what action should be taken.

AS 3.1.33



© 2021

Lloyd's Register
Foundation

010766-010776-0091