

21 DEC 1932

Chief Surveyors So. 12.32 Received from Chief Surveyors \_\_\_\_\_

SHIP NAME M. S. K. "Cierito" Report Bdz No. 1339

**For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SUPERVISOR.~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)

2nd No. 1 SURVEY PARTLY HELD.

11.31 When proposed to be completed \_\_\_\_\_

Survey held, &c. \_\_\_\_\_


The class is subject to repairs being effected to chafed shell plating on port and starboard sides.

The 2nd S.S.No.1, due 11,31, has been partly held (for what remains to complete see Cadiz report No. 1339) and Cadiz letter dated 28.10.32).

Some repairs are required.

Action has been deferred, and, in reply to enquiry, the Cadiz Surveyor now states that the Owner has promised to have the vessel ready for completion of Special Survey in about a fortnight or three weeks time.

It is submitted action be deferred.

  
20.12.32



© 2021

Lloyd's Register Foundation

010766-010776-0093