

18 JAN 1963

Ship's name CHOPIN

Port GdK


No. m. 1143

Last survey date 28.12.62

Class is subject to nil

Small crack in the welding of distance
piece of auxiliary boiler blowdown
seawater to the ship's side. Surveyor
recommends distance piece for aux.
boiler blowdown seawater repaired by
a cement box be examined and
dealt with as necessary at next day-
docking

*It is submitted that this
vessel is eligible to remain
as CLASSED.* subject as above



18/1/63

© 2021

Lloyd's Register
Foundation