

Less Engine Room
Less Navigation Spaces
Register Tonnage
as cut on Beam ...
Feet.
LENGTH on Deck
as per Rule 303

2500, 12, 10.
1

Sent to Chief Surveyors.

N. N. HERVAL,

Received from Chief Surveyors

VESSEL'S NAME Steel S. S. "ALVARADO" Report Qls. No. 40537

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.) - Extract from Sub-Committee's Report, 24.5.92.

Nature of Survey


When due

The Downton Pump has been dispensed with for the present, but it is concluded the Owners are agreeable to fit same when requested.


100 A.1. (steel)
2 Dks (steel)

Cell DB 260' 661t. FPT 94t APT 180t.

FK. GBH. pl. cons. Woyds AYC.P. P33, B81, F32



M
AtB.
A-11-20



© 2021

010835-010845-0090

Lloyd's Register
Foundation

Brackets at int
Height of Out
INNER BOTTOM P
thickness

Gen. 2.