


COPY
LLOYD'S REGISTER OF SHIPPING



Port Genoa

19th July, 1963

This is to Certify that I have surveyed part of the machinery
of the **s/s "LOBITO"** **5419 Gross tons** of Panama
for **MBS & Machinery repairs whilst the ship lay afloat at this port**
on 15th July and subsequently.

and that all my recommendations have been carried out to my satisfaction. I
am reporting accordingly and recommending to the Committee of Lloyd's Register
of Shipping that the machinery classification should be retained and the following
survey records assigned **MBS 5.63** when the Survey has been completed, subject
to any conditions attached to the ships class being dealt with as previous-
ly recommended.

Parts now examined:—

The stbd. boiler examined throughout externally & internally with all its
mountings.

The centre & stbd. boiler's safety valves adjusted under steam, their oil
burning system & remote controls examined.

To complete the MBS:

The port boiler remain to be examined throughout its safety valves to be
adjusted under steam.

Scama
(S. CEUNA)

Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
CSM Continuous Survey of Machinery
DBS Donkey Boiler Survey
ES Engine Special Survey

MBS Main Boiler Survey
OF Fitted for oil fuel (date) FP above 150° F.
SGS Steam Generator Survey
SPS Steampipe Survey

TS Tailshaft Survey
TS(CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."